

CTFD Maintenance Repair List

April 22, 2014

Engine 42

- Pump Panel Lights to be replaced - TRM

Engine 42-1

- Foam Pump/System OOS. Will not be repaired
- Inspection by end of May

Reserve 42

- Cab cylinder locks are leaking hydraulic fluid – Glick ordered

Tanker 42

- New 3" Storz adapters ordered
- Dump Tank Latch broken, needs repaired
- Rear Dump switch, wiring needs repaired
- Right Discharge Leaking

Tanker 42-1

Rescue 42

- Lightbar repaired by TRM 4-17-14

Tower 42

- Q2B Siren, OOS.
- Sutphen annual service contract to be performed 4-23-14, unit will be out of service.
Punch list of items to be repaired at this time.....

Brush 42

Utility 42

Utility 42-1

Brush 42-2

- Inspection by end of May
- Missing bolts on winch were replaced

Car 42

FC34

Station 2 has 2 Cascade Cylinders out for hydro, April 22, 2014

Station 3 has 4 Cascade Cylinders out for hydro, April 22, 2014

Pump Testing scheduled for May.

Ladder Testing Completed April 9, 2014

Pump Service on all pumps to be scheduled